

GPS instructions for Doc

1. Press **On/off** button and **hold** until the start screen is displayed.
2. A numbers screen is highlighted, press **Enter**.
3. The number screen appears, press **Waypoint** button.
4. Waypoint screen appears, press **Arrow** button twice to scroll down to **Man Overboard**.
5. When Man Overboard is highlighted **and you are positioned at the bottom mark** (mark 3), press **Enter**.
6. Navigation to MOB screen appears, press **Enter**.
7. Navigation chart appears with small numbers. If you wish to see larger numbers, press **Return**.
8. Start screen comes up, press **Enter** to see the large number screen.
9. When you now drive away from MOB (mark 3) the screen shows the bearing and the distance (first in meters then in nautical miles) to MOB (mark 3).
10. Drive into the direction of the wind reading, towards mark 1 (top mark). Use the compass and pick a point in the distance to drive to. While under way the GPS shows the growing distance and back bearing to MOB (mark 3).
11. Upon arrival at the mark 1 position the GPS shows the distance and the bearing from mark 1 to mark 3. Check this bearing with the compass. Drop mark 1.
12. Do NOT press MOB again but use the compass and head towards mark 2 (gybe mark).
13. Drive into the direction of mark 2 until the GPS shows the correct distance and bearing to MOB (mark 3). The distance is the same as from mark 1 to mark 3.
14. Use the compass to check the bearing from mark 2 to mark 1 and the bearing from mark 2 to mark 3. Drop mark 2.
15. When returning Doc to shore switch off the GPS by pressing the on/off button until the screen is dark.

